

Site	Number and type of operating theatre	Number of beds within Critical/ Intensive care unit	Number of Endoscopy treatment rooms/ theatre	Number of resuscitation areas within A&E	Make, model and age of equipment listed*
<b>Bishop Auckland Hospital (BAH)</b>	4 UCV 1 conventional	0	2	0 (1 in minor injuries)	1.0 Ultra clean ventilation systems - Howarth 2 years old  2.0 General Theatres Standard duct and grill fed from an filtered AHU 16 years old  3.0 Ceiling mounted medical service pendants - Beacon Medaes pendants 2 years old  4.0 Operating lights - Maquet operating lights  5.0 Theatre control panels - Brandon  6.0 Isolation Rooms - 0 dedicated  7.0 AHU Units - 18  8.0 Class 1 , 2 & 3 Cabinets - 0  9.0 Clean rooms – None
<b>Darlington Memorial Hospital (DMH)</b>	Theatre 1 Ophthalmology  Theatre 3 General  Theatre 4 General	ITU 1 – 8 beds: 4 General beds and 4 Isolation beds  ITU 2 – 5 beds: 5 General beds	Endoscopy Treatment rooms – 2 rooms: 2 Treatment rooms	A&E Resus – 2 areas, 4 beds: Adult: 3 beds Paediatrics: 1 bed	1.0 UCV: MAT = <5 years old  2.0 3 General Theatres and 2 Laparoscopic/ General  3.0 Ponta Beams = Drager = <7 years old

	<p>Theatre 5 General</p> <p>Theatre 6 UCV</p> <p>Theatre 7 UVC</p> <p>Theatre 8 UVC</p> <p>Theatre 9 UVC</p> <p>Theatre 10 UVC / Laproscopy</p> <p>Theatre 11 Laparoscopic / General</p> <p>Theatre 12 Laparoscopic / General Maternity Theatre</p>	<p>CCU – 8 beds: 4 siderooms 2 2 bed rooms</p>			<p>Pendants = Starkstrom = &lt;1 year old Pendants = Steris = &lt;6 years old</p> <p>4.0 Operating Lights = Steris = &lt;6 years old Operating Lights = KLS Martin = &lt;1 year old</p> <p>5.0 TCP = Bender = &lt;6 years old TCP = Starkstrom = &lt;1 year old</p> <p>6.0 4 Isolation beds</p> <p>7.0 AHU = Barkel = &lt;7 years old AHU = Air Handling Systems = &lt;1 year old</p> <p>8.0 Cabinets = 3 (best guess not maintained by Estates)</p> <p>9.0 Clean Rooms = 3 (excluding Theatres)</p> <p>10.0 Contracts = various with suppliers and in house.</p>
<p><b>Shotley Bridge Hospital (SBH)</b></p>	<p>1 Operating Theatre: Theatre 1 General</p> <p>1 Treatment room: Clinical procedures room (next to Theatre 1)</p>	<p>0</p>	<p>1 Endoscopy Treatment room: 1 Treatment room</p>	<p>0</p>	<p>1.0 UCV: None</p> <p>2.0 1 General Theatre</p> <p>3.0 Ponta Beams: None Pendants: None</p> <p>4.0 Operating Lights: Peacocks, 8 years old</p> <p>5.0 TCP: unknown, &gt;20 years old</p> <p>6.0 0</p>

					<p>7.0 AHU: unknown, &gt;20 years old</p> <p>8.0 Cabinets: None</p> <p>9.0 Clean rooms: None (excluding Theatres)</p> <p>10.0 Contracts: various with suppliers and in house</p>
<p><b>University Hospital of North Durham (UHND)</b></p>	<p>3 UCV 1 Vascular 6 Conventional 1 Maternity</p>	<p>ITU: 10 beds, of those 10 beds 4 are HDU.</p> <p>Acute Cardiac Unit (what used to be Coronary Care Unit): 8 monitored beds (note level 2)</p>	<p>Endoscopy Treatment rooms: 2</p>	<p>3</p>	<p>1.0 Ultra clean ventilation systems – MAT canopy approx. 19 years old.</p> <p>2.0 General Theatres – Standard duct and grilles fed from Barkell AHU F7 filtration. Approx 19 years old.</p> <p>3.0 Ceiling mounted medical service pendants – Beacon Medaes pendants, 19 years old. Flexi hoses replaced 4 years ago.</p> <p>4.0 Operating lights – Conventional theatres and UCV Maquet Volista operating lights 4 years old. Vascular theatre Trumpf operating light, approx.. 4 years old</p> <p>5.0 Theatre control panels – MAT panels</p> <p>6.0 Isolation Rooms - 20</p> <p>7.0 AHU Units – Barkell AHU's approx. 19 years old.</p> <p>8.0 Class 1, 2 &amp; 3 Cabinets – Trust equipment</p>

					<p>9.0 Clean rooms – CSSD packing room.</p> <p>10 .0 Details of any service contracts in place for this equipment Specialist contractors visit annually for items 1 to 5 and 8 and 9 above. PPM's in place for items 6 and 7. AHU's</p>
--	--	--	--	--	---

\*

- 1.0 Ultra clean ventilation systems
- 2.0 General Theatres
- 3.0 Ceiling mounted medical service pendants
- 4.0 Operating lights
- 5.0 Theatre control panels
- 6.0 Isolation Rooms
- 7.0 AHU Units
- 8.0 Class 1, 2 & 3 Cabinets
- 9.0 Clean rooms
- 10 .0 Details of any service contracts in place for this equipment